



Chemicals Assessment &
Management Division
Groundwater Protection Branch



Room 2,79, 2nd floor
Provincial Building
200 - 5 Avenue S
Lethbridge, Alberta
Canada T1J 4L1

Telephone 403/381-5456
Fax 403/382-4428

May 8, 1996

FILE #: 4040-BA04-1

Mr. Bradley Mersereau, P.Eng.
Canadian Turbo Inc.
630 - 4 Avenue SW
Calgary, Alberta
T2P 0J9

Dear Mr. Mersereau:

Re: Barons Turbo Bulk Plant and Barons Hardware Store

I have reviewed the September 17, 1993 Seacor report for this site. The site investigation shows that subsurface petroleum hydrocarbon contamination exceeding the risk management criteria of the draft 1994 "Remediation Guidelines for Petroleum Storage Tank Sites" was discovered upgradient from the hardware store, near the pump island and under the southeast corner of the building.

To date, the extent and degree of the contamination have not been fully evaluated. Since this site was supplied by Canadian Turbo at the time the contamination was discovered, I am seeking your co-operation in assessing the remedial options for these sites. I would appreciate a response by June 1, 1996. I suggest that we meet with the owners of the hardware store property to discuss the remedial proposals. Please call me at 381-4255 to arrange a meeting time.

Thank you for your prompt attention to this situation.

Yours truly,


Don Wyrostock

DW/tlm


5/9/96